

Catalyst Chart

Ratio of Catalyst for Polyester Resin and Coatings

Volume	1% for resin		2% for coating	
	CC	OZ	CC	OZ
8 ounces	2.5	0.06	5	0.13
32 ounces (QT)	10.0	0.33	20	0.67
128 ounces (1 Gal)	40.0	1.25	80	2.50

Caution: KEEP AWAY FROM CHILDREN

Keep away from acids, sanding dust, copper, brass, iron, bases and promoters.

Store in original closed container at recommended storage temperatures.

Organic Peroxides can decompose explosively.

Always wear safety glasses and protective gloves.

Keep away from heat, sparks, and open flames

1-909 259-5000

